


# EZ AIR PRO SHIELD P APR (9934) EZ AIR PRO BLUE WELDING HELMET P APR (9934-W) EZ AIR PRO BLACK WELDING HELMET P APR (9934-WB)



Key	Part #	Description	Key	Part #	Description	Key	Part #	Description
	<b>9934</b>	<b>EZ Air Pro Shield P APR</b>	8	PR02-623SP	HEPA Filter (Set of 2)	14	9904-33	Replacement #10 Lens Kit (9904-WB)
	<b>9934-W</b>	<b>EZ Air Pro Blue Weld. Helmet P APR</b>	9	9904-04	Neck Shroud	15	9904-35	Replacement ADF Kit (9934-WB)
	<b>9934-WB</b>	<b>EZ Air Pro Black Weld. Helmet P APR</b>	10	9904-03	Head Suspension/Cradle Assy.	16	9904-22B	Welding Shield Attachment Kit (for 9904-W, 9904-WB) (R & L Sides)
1	9904-10	EZ Air Pro Shield	11	9904-03LK	Head Lining Brow Pad Kit	17	PR02-621SP	Battery Charger
2	9904-10W	EZ Air Pro Blue Welding Helmet	12	9904-25	Lens Covers 6/pk (for 9934)	18	PR02-630SP	P APR Assembly w/o Headtop
3	9904-10WB	EZ Air Pro Black Welding Helmet	13	9904-36	Replacement ADF Kit (9934-W)	<b>Accessories - Not Shown</b>		
4	PR02-625SP	Breathing Tube	13a	9904-22W	Replacement Outer Lens (for 9934-W)		9935-IP	International Plug Kit
5	PR02-627SP	Waist Belt	13b	9904-22V	Replacement Inner Lens (for 9934-W)		PR02-624SP	Acid Gas Filter (Set of 2)
6	PR02-622SP	Blower					PR02-629SP	Organic Vapor Filter (Set of 2)
7	PR02-620SP	Battery					9904-09C	Visor Lock Clip (Sold Separately)